DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-025041 Address: 333 Burma Road **Date Inspected:** 03-Jun-2011

City: Oakland, CA 94607

OSM Arrival Time: 1500 **Project Name:** SAS Superstructure **OSM Departure Time:** 300 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Mr. Li Yan Hua No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Baskar Govindarajan, was present during the times noted above for observations relative to the work being performed.

OBG-Trial assembly Yard

This QA Inspector observed the following work in progress,

Shielded Metal Arc Welding (SMAW)

Weld joint- 064 Located on Segment 13AE, SEG3007AH. Welder is identified as 043661. ZPMC Quality Control Inspector (QC) is identified as Zhan Hai Feng. The welding variables recorded by QC appeared to comply with the WPS-B-P-2213-TC-U4B-FCM-1.

Flux cored Arc Welding (FCAW)

Weld joint- 047, 048 Located on Segment 14W, Deck plate to stiffener SEG3020AF. Welder is identified as 045175. ZPMC Quality Control Inspector (QC) is identified as Zhu Lin. The welding variables recorded by QC appeared to comply with the WPS-B-T -2132 –Esab.

Weld joint- 062, 063 Located on Segment 14W, Deck plate to stiffener SEG3020AF. Welder is identified as

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

048696. ZPMC Quality Control Inspector (QC) is identified as Zhu Lin. The welding variables recorded by QC appeared to comply with the WPS-B-T -2132 –Esab.

Weld joint- 158, 159 Located on Segment 14W, Deck plate to stiffener SEG3020AF. Welder is identified as 045175. ZPMC Quality Control Inspector (QC) is identified as Zhu Lin. The welding variables recorded by QC appeared to comply with the WPS-B-T -2132 –Esab.

Magnetic Particle Testing (MT)

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No. 09354

This QA inspector performed (MT) of approximately 15% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated a TL 6028 MT report for this date. The member is identified as OBG Lift 13AE components. The weld designations reviewed are as follows:

3015 TR2 -001 – Jt. nos -003, 004 3016 TR1 -001 – Jt. nos -001, 002

3013 TR1 -001 – Jt. nos -001, 002

For further information's, see the pictures below:

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.





WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Summary of Conversations:

No relevent Conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (15000422372), who represents the Office of Structural Materials for your project.

Inspected By:	Baskar, Govindarajan	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer